

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight

DHR Id#: 046-0100

Resource Identification

Property Name(s): House, Route 635 {Function/Location}
Property Date: 1910
Address(s): Route 635 {Current}
County/Independent City: Isle Of Wight
Vicinity of: Windsor
State, Zip: Virginia
USGS Quad Name: WINDSOR

National Register Eligibility Status

Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Component Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	other	Brick	
Foundation		Concrete	
Porch	Porch - 1-story, 3-bay	Wood	Porch - Columns, Square
Roof	Roof - Hipped	Metal	Rcof - Standing Seam
Structural System	Structural System - Frame	Wood	other
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6

WUZIT Count:

No.	Wuzit Types	Historic?
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: Single Dwelling

Est. Date of Construction: 1910 ca {VDHR Survey File}

Accessed?

Primary Resource? Yes

Number of Stories: 2.0

Interior Plan Type: Central Passage, Double Pile

Threats to Resource:

Description: Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior

Description: End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): Domestic

Significance Statement: House built at the same time earlier dwellings in area were undergoing 1 renovation.

Bibliographic Documentation

Ownership Information

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight

DHR Id#: 046-0100

Graphic Media Documentation

<u>Medium</u>	<u>Depository ID #</u>	<u>Photo Depository</u>	<u>Date</u>	<u>File Name</u>
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: Reconnaissance Survey
Date: 1990/7 /4
Organization or Person: Willie Graham
CRM Event Notes or Comments:



VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF
SURVEY FORM

File no. 46-100
Negative no(s).

City/Town/Village/Hamlet <u>Windsor Vicinity</u> Street address or route number <u>Rte 635, .78 mi. east of</u> Historic name <u>Rte. 610</u>	County <u>Isle of Wight</u> U.S.G.S. Quad <u>Windsor</u> Common name _____
Present use <u>Abandoned</u> Original use <u>Dwelling</u>	Building Style _____ Building Date(s) <u>ca. 1910</u>

1. Construction Materials

- ☒ wood frame
☐ brick
 bond: ☐ English
 ☐ Flemish
 ☐ _____-course American
 ☐ stretcher
 ☐ other _____
- ☐ stone
 ☐ random rubble
 ☐ coursed rubble
 ☐ ashlar ☐ dressed
 ☐ rock-faced
- ☐ log:
 ☐ squared ☐ unsquared
 notching:
 ☐ V-notch ☐ half dovetail
 ☐ saddle ☐ full dovetail
 ☐ square ☐ diamond
- ☐ concrete block
☐ terra cotta
☐ steel frame
☐ other _____

2. Cladding Material

- | | |
|--|---|
| ☐ weatherboard
☐ vertical siding
☐ board & batten
☐ shingle:
☐ wood
☐ asbestos
☐ asphalt
☐ bricktex
☐ other _____ | ☐ composition siding
☐ stucco
☒ aluminum or vinyl siding
☐ cast iron
☐ sheet metal
☐ enameled metal
☐ glass |
|--|---|

3. Stories (number) 2
☐ low basement ☐ raised basement

4. Bays (number): front 3 side (church) _____
☐ symmetrical ☐ asymmetrical

5. Roof Type
☐ shed ☒ hipped
 ☐ parapet? ☐ pyramidal?
☐ gable ☐ mansard
 ☐ pediment? ☐ false mansard
 ☐ parapet? ☐ gambrel
 ☐ clipped end? ☐ flat
 ☐ cross gable? ☐ parapet?
 ☐ central front gable? ☐ roof not visible
☐ other _____

6. Roofing Material

- ☐ shingle
 ☐ composition (asphalt, asbestos, etc.)
 ☐ wood
☒ metal
 ☒ standing seam
 ☐ corrugated
 ☐ pressed tin (simulated shingles)
☐ tile
 ☐ pantile ☐ flat ☐ glazed
☐ slate
☐ not visible

7. Dormers (number): front _____ side _____
☐ gable ☐ pediment?
☐ shed
☐ hipped

8. Primary Porch

style _____
stories 1
levels 1 bays 3
materials wood, standing seam tin
description and decorative details
Hipped roof, square columns, exposed eaves.

9. General supplementary description and decoration: Six-over-six sash, exposed rafter ends, exterior brick chimney, concrete foundations.

10. Major additions and alterations:
Aluminum siding.


11. Outbuildings:

12. Landscape Features:

13. Significance: House built at same time earlier dwellings in area were undergoing renovation.

Surveyed by: Willie Graham

Date: 7/4/90



Map




FIGURE 9
Architectural Resources Identified During Survey